



# GOLF LASER RANGING TELESCOPE USER MANUAL



## Product Overview



## Operating Instructions And Settings

### Eyepiece

Eyepiece focus is adjustable (as shown below)  
Turn the focusing ring clockwise or counterclockwise to get the best focus for your eyes.



### Battery Level

When the low battery indicator symbol is displayed, it indicates that the battery is low and needs to be recharged in time.




### Power Switch

1. Press the power/start button to instantly start the rangefinder
2. After 20 seconds of inactivity, the rangefinder will automatically power off.




### How To Use The Buttons

1. Short press the mode key to switch the measurement mode
2. Long press mode key to switch unit
3. Short press the measurement key for distance measurement



## LED Display



- ① Golf Mode
- ② Flagpole Golf Ranging
- ③ At the same time, lock the flag
- ④ Straight line distance
- ⑤ Height measurement
- ⑥ Compensation distance
- ⑦ Angle

Angle toggle off—red display indicates off

Mode	Icon Display
Distance-only Mode	
Flagpole scanning mode (without angle)	

Angle toggle on—shows green to indicate on

Mode	Icon Display
Flagstick Scan Mode	
Golf Compensation Mode	
Altimeter Mode	
Leveling Mode	

## Product Specification

Magnification	6X
Field of view	7°
Objective	25mm
Eyepiece	16mm
Diameter of exit pupil	3.9mm
Laser Type	905nm
Lens Coating	Fully Multi-Coated (FMC)
Battery	Li-ion battery (3.7V)
Measuring time	0.5-1sec
Measurement accuracy	±0.5m
Measuring distance	5-600/800/1000/1200/1500m
Net weight	134g/163g (belt clip)
Dimension	97*66*39mm
Product Resolution	±0.1m
Working Temperature	-20 C-50 C
Operating Humidity	≤80%
Low Battery Indication	Yes
Flagpole Lock	Yes
Scanning Mode	Yes
USB charging port	Yes
Magnetic belt clip	Yes
External Dimensions of Color Box	137×108×67mm
Outer Dimension of Outer Package	455×290×355mm
Total weight of a box of 40	12.92kg(without belt clip)/ 14.12kg(belt clip)

## Caveat

- In order to protect the mirror coating, please do not touch the lens surface with your hands.
- The laser rangefinder has been accurately calibrated by the instrument, please do not disassemble it by yourself. If repairs are required, please return the unit to your dealer.
- If the lens becomes dirty, please gently wipe it with a clean cloth and do not use other objects to wipe it.
- Avoid collision and heavy pressure when carrying or using, especially keep away from high temperature and corrosive substances.
- Keep away from humid environment during storage, please put the device in a dry, well-ventilated place and avoid direct sunlight, dust and temperature changes.
- Rain and fog can affect the laser path and may cause measurement errors. In case of bad weather, it may lead to measurement errors.

## Warnings

- Do not look directly into the laser beam.
- Looking directly into the sun with this device may permanently damage your eyes!
- Do not aim the device at the sun, as this could damage the internal components of the device.
- Keep the eyepiece away from direct sunlight.
- Do not place the device outside the temperature range of -10° to 60°.

## Packing List

Rangefinder *1	Strap*1	Instruction manual *1
Charging cable *1	Cleaning cloth *1	Color box *1